



IECEX Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.: **GB/SIR/QAR09.0010/11**

Page 1 of 1

QAR Free Ref. No.: **80030987**

Status: **Issued**

Details of change: **New location**

Date of issue: **2020-01-28**

Site(s) audited: **Dixon Bayco**
7280 Union Center Boulevard
West Chester
OH 45014
United States of America

Valid until: **2021-06-30**

Audit date: **2020-01-10**

Issuing ExCB: **SIR - SIRA Certification Service**

Manufacturer: **Dixon Bayco**
7280 Union Center Boulevard
West Chester
OH 45014

Location of Manufacturer: **United States of America**

Product information: **Liquid Level Sensors**

Protection concept: **Ex ia Ex d**

Related QARs:

[GB/SIR/QAR09.0010/00](#)
[GB/SIR/QAR09.0010/03](#)
[GB/SIR/QAR09.0010/06](#)
[GB/SIR/QAR09.0010/09](#)

[GB/SIR/QAR09.0010/01](#)
[GB/SIR/QAR09.0010/04](#)
[GB/SIR/QAR09.0010/07](#)
[GB/SIR/QAR09.0010/10](#)

[GB/SIR/QAR09.0010/02](#)
[GB/SIR/QAR09.0010/05](#)
[GB/SIR/QAR09.0010/08](#)

Related Certificates (manual insertion):

Related Certificates (automatic linking):

Related Certificates for previous versions:

IECEX SIR 09.0013X issue: 0
IECEX SIR 09.0013X issue: 3
IECEX SIR 09.0013X issue: 6
IECEX SIR 09.0014X issue: 2
IECEX SIR 09.0014X issue: 5
IECEX SIR 09.0015X issue: 1
IECEX SIR 09.0015X issue: 4
IECEX SIR 09.0016X issue: 2
IECEX SIR 09.0017X issue: 1
IECEX SIR 09.0017X issue: 4
IECEX SIR 14.0100X issue: 2

IECEX SIR 09.0013X issue: 1
IECEX SIR 09.0013X issue: 4
IECEX SIR 09.0014X issue: 0
IECEX SIR 09.0014X issue: 3
IECEX SIR 09.0014X issue: 6
IECEX SIR 09.0015X issue: 2
IECEX SIR 09.0016X issue: 0
IECEX SIR 09.0016X issue: 3
IECEX SIR 09.0017X issue: 2
IECEX SIR 14.0100X issue: 0
IECEX SIR 19.0052X issue: 0

IECEX SIR 09.0013X issue: 2
IECEX SIR 09.0013X issue: 5
IECEX SIR 09.0014X issue: 1
IECEX SIR 09.0014X issue: 4
IECEX SIR 09.0015X issue: 0
IECEX SIR 09.0015X issue: 3
IECEX SIR 09.0016X issue: 1
IECEX SIR 09.0017X issue: 0
IECEX SIR 09.0017X issue: 3
IECEX SIR 14.0100X issue: 1

Comments: